





Borate ppm					
0	15	30	50	80	



Immerse strip for 5 seconds. Remove with **pad face up**.
DO NOT SHAKE OFF EXCESS WATER. Wait 15 seconds
and compare to color chart.

- Keep wet fingers out of the bottle. Close cap tightly.
- In pools, immerse strip to a depth of 6".
- In spas, turn off jets and immerse strip to a depth of 6".
- Store in a cool, dry place.



LaMotte Company, Chestertown, MD 21620 USA
www.lamotte.com/insta



Code 3017-G

